

## Monthly Progress Report For May 2012

Removing of loose plaster completed at facades of both side except front façade.

P U grouting completed at the soffit of the roof slab. Water proofing cementaceous application is in progress on the roof slab.

Demolition of the timber floor at 2<sup>nd</sup> STY is in progress. Partition at the entrance of Galleria was completely removed.

Construction of the condeck slab was completed at the right wing of the conserved building.

Epoxy injection for the repair of the crack at soffit of 2<sup>nd</sup> STY slab in progress.


Erection of the light weight concrete for the toilet at 1<sup>st</sup> Storey completed. Repairing of the opening of the entrance to the bar completed. Forming the wall along the staircase 04 is in progress.

Drain works completed at the both side of the conserved building.

Repairing of the features of the building is in progress. Construction of ramp completed at the basement.

Removing of the dust & loose paint by using water jet was completed at the basement. Applying Antifungal paint is in progress. Demolition of existing staircase to the basement was completed.

ACMV work start on the 28<sup>th</sup> of May, in progress.



P U grouting completed at the soffit of roof slab.  
progress

Water proofing cementaceous application is

Monthly Progress Report For May 2012



Construction of ramp at basement completed.



Drain works completed at both side of the



Construction of toilet at 1 St Storey completed.



Condeck slab at right wing completely con

Monthly Progress Report For May 2012



Clean the crack & prepare for Epoxy injection at the 2<sup>nd</sup> STY slab soffit.



Existing staircase to basement was completely



Removing of the partition at 2<sup>nd</sup> STY entrance t  
completed

Monthly Progress Report For May 2012



Repairing of the features is in progress.



Removing of old plaster & re-plastering in prog



Removing of plaster at façade completed excep

Monthly Progress Report For May 2012



ACMV work start on the 28<sup>th</sup> of May



Forming break wall in progress at ST-04



Epoxy injection at crack line in progress